



## Tipus P xapes soldables

### Xapes soldables Tipus P

Les xapes soldables aporten una perfecta oclusió al tub un cop soldades. N'hi ha tant per a tubs rectangulars com per a quadrats.

[Accés catàleg](#)



### Informació tècnica

Chapas Soldables						
	D M 8	D M 10	D M 12	D M 16	D M 20	D M 24
25 x 25 mm						
30 x 30 mm			44310P303012			
35 x 35 mm						
40 x 40 mm			44310P404012	44310P404016	44310P404020	
45 x 45 mm						
50 x 50 mm			44310P505012	44310P505016	44310P505020	
60 x 60 mm						
70 x 70 mm						

80 x 80 mm						
100 x 100 mm						44310P999924
50 x 25 mm		44310P502510				
50 x 30 mm						
60 x 30 mm						
60 x 40 mm						
80 x 40 mm						
80 x 50 mm						
80 x 60 mm						
100 x 50 mm						